

# Stick Welding Basics: Settings, Polarity, Techniques

Stick welding, formally known as Shielded Metal Arc Welding (SMAW), is the most portable and versatile welding process. This guide covers essential settings, polarity selection, and fundamental techniques for successful stick welding across various applications.

## 1. Understanding Polarity - The Foundation

Polarity determines the direction of electrical current flow and profoundly affects penetration, deposition rate, and electrode performance. Stick welding uses two polarities:

| Polarity                            | Connection                  | Heat Distribution         | Best For                                           | Characteristics                                            |
|-------------------------------------|-----------------------------|---------------------------|----------------------------------------------------|------------------------------------------------------------|
| DCEP<br>(DC+)<br>Electrode Positive | Electrode to +<br>Work to - | 70% electrode<br>30% work | Deep penetration<br>Most common<br>6010, 7018, 309 | Maximum penetration<br>Cleaner welds<br>Stable arc         |
| DCEN<br>(DC-)<br>Electrode Negative | Electrode to -<br>Work to + | 30% electrode<br>70% work | Thin materials<br>Surfacing<br>7024, hardfacing    | Fast deposition<br>Minimal penetration<br>Flatter bead     |
| AC<br>Alternating Current           | Switches<br>120x/second     | Balanced<br>50/50         | General purpose<br>6011, 6013<br>Stick conditions  | Moderate penetration<br>Arc blow resistant<br>All-position |

## 2. Electrode Selection Guide

### Understanding AWS Electrode Classification:

Example: E7018 breaks down as: E = Electrode, 70 = 70,000 PSI tensile strength, 1 = all-position capable, 8 = low-hydrogen iron powder coating, DCEP or AC.

| Electrode | Polarity   | Penetration | Applications                       | Key Features                                 |
|-----------|------------|-------------|------------------------------------|----------------------------------------------|
| E6010     | DCEP only  | Deep        | Pipe, root passes, dirty metal     | Aggressive arc, all-position, spray transfer |
| E6011     | AC or DCEP | Deep        | General purpose, farm/field        | Similar to 6010, works on AC machines        |
| E6013     | AC/DC Both | Light       | Sheet metal, body work             | Easy striking, smooth arc, low penetration   |
| E7014     | AC/DC Both | Medium      | Production welding, fast fill      | Iron powder, high deposition, drag technique |
| E7018     | AC/DCEP    | Medium-Deep | Structural steel, pressure vessels | Low hydrogen, smooth arc, code quality       |
| E7024     | AC/DCEN    | Shallow     | Flat/horizontal fillets, fast      | Very high deposition, drag rod technique     |
| E308L-16  | DCEP       | Medium      | Stainless steel (304)              | Stainless rod, low carbon version            |

## 2025 Best Welding Helmet Reference Guide

|          |      |        |                                      |                                 |
|----------|------|--------|--------------------------------------|---------------------------------|
| E309L-16 | DCEP | Medium | Dissimilar metals, mild to stainless | Versatile, higher alloy content |
|----------|------|--------|--------------------------------------|---------------------------------|

### 3. Amperage Settings Chart

Amperage selection depends on electrode diameter, position, and joint configuration. These are starting points—adjust based on arc behavior and weld appearance:

| Electrode Size | Flat/Horizontal | Vertical Up | Vertical Down | Overhead        |
|----------------|-----------------|-------------|---------------|-----------------|
| 1/16" (1.6mm)  | 20-40 A         | 20-35 A     | 25-40 A       | 20-35 A         |
| 5/64" (2.0mm)  | 30-50 A         | 30-45 A     | 35-50 A       | 30-45 A         |
| 3/32" (2.4mm)  | 60-90 A         | 55-80 A     | 65-90 A       | 55-80 A         |
| 1/8" (3.2mm)   | 90-150 A        | 80-130 A    | 100-150 A     | 80-120 A        |
| 5/32" (4.0mm)  | 140-200 A       | 120-180 A   | 150-200 A     | 120-170 A       |
| 3/16" (4.8mm)  | 180-275 A       | 160-240 A   | 200-275 A     | Not recommended |
| 1/4" (6.4mm)   | 275-425 A       | Flat only   | Flat only     | Not recommended |

#### Amperage Adjustment Guidelines:

- Too Low: Electrode sticks frequently, arc sputters, poor penetration, convex bead
- Too High: Excessive spatter, undercut, fast electrode consumption, burn-through on thin material
- Correct: Stable arc sound (like bacon frying), electrode melts smoothly, good penetration, slight convex bead
- Rule of Thumb: 1 amp per .001 inch of electrode diameter (1/8" = 125 amps as starting point)

### 4. Fundamental Welding Techniques

#### Arc Starting Methods

Scratch Start (recommended for beginners): Drag electrode across work like striking a match, then lift slightly to establish arc length. Tap Start: Touch electrode perpendicular to work, then lift quickly. Avoid jabbing—creates slag inclusions.

#### Arc Length Control

- Correct Arc Length: 1x electrode diameter (1/8" rod = 1/8" arc gap)
- Too Short: Electrode sticks, arc goes out, poor penetration
- Too Long: Spatter increases, unstable arc, poor penetration, wide inconsistent bead
- Listen: Tight arc = smooth, steady crackle; loose arc = irregular popping
- Visual: Proper arc length creates focused, intense white cone at electrode tip

#### Travel Speed and Angle

Work Angle: Perpendicular to joint (90°) for equal penetration on both sides. Travel Angle: 5-15° drag (electrode pointing backward) for most applications. Push angle used only for specific applications like thin materials or vertical down. Speed: Move consistently—too fast creates narrow, weak bead with poor penetration; too slow causes excessive buildup and possible burn-through.

5. Position-Specific Techniques

| Position             | Electrode Angle                                                    | Technique                                            | Common Issues                                     |
|----------------------|--------------------------------------------------------------------|------------------------------------------------------|---------------------------------------------------|
| Flat (1G, 1F)        | 90° work, 5-15° drag                                               | Straight stringer or slight weave, consistent travel | Sagging bead if too slow, undercut if too fast    |
| Horizontal (2G, 2F)  | 90° work, 5-10° drag, slight upsway for small weave, watch for sag | Swag for small weave, watch for sag                  | Overlap on bottom, undercut on top                |
| Vertical Up (3G, 3F) | 90° work, 5-10° push up                                            | Tight zigzag or triangular weave, pause at sides     | Incomplete fusion, uneven bead if too fast        |
| Vertical Down        | 90° work, 30-45° drag down                                         | Fast travel, straight stringer, no weave             | Slag inclusion if too slow, cold lap if too fast  |
| Overhead (4G, 4F)    | 90° work, 5-15° drag                                               | Small diameter rod, fast travel, stringer preferred  | Spatter, sagging weld metal, burns through jacket |

## 6. Common Problems and Solutions

| Problem                     | Cause                                                | Solution                                                             |
|-----------------------------|------------------------------------------------------|----------------------------------------------------------------------|
| Electrode sticks repeatedly | Amperage too low, arc too short, poor ground         | Increase amperage 10-15A, maintain proper arc length, check ground   |
| Excessive spatter           | Amperage too high, arc too long, wrong polarity      | Reduce amperage, shorten arc, verify polarity for electrode type     |
| Porosity in weld            | Moisture in electrode, dirty base metal              | Use dry electrodes from proper storage, clean metal, shield from air |
| Undercut at weld toe        | Amperage too high, travel too fast, improper angle   | Reduce amperage, slow travel speed, adjust work angle to 90°         |
| Incomplete penetration      | Amperage too low, travel too fast, joint not beveled | Increase amperage, slow travel, ensure proper joint preparation      |
| Cracking in weld            | High carbon steel, rapid cooling, wrong electrode    | Preheat base metal, use low-hydrogen rod (7018), reduce cooling rate |

## 7. Electrode Storage and Handling

Low-hydrogen electrodes (E7018, E7016) absorb moisture from air, causing porosity and cracking. Proper storage is critical:

- Store unopened cans in dry location at 40-120°F
- Once opened, store E7018 in rod oven at 250-300°F
- E6010, E6011, E6013 can be stored at room temperature in dry location
- Discard E7018 rods exposed to atmosphere for over 4 hours
- Re-dry E7018 at 650-750°F for 1 hour if moisture exposure suspected
- Never re-dry electrodes more than once—flux becomes brittle
- Use rod quiver or insulated holder to keep rods hot during use
- Do not mix electrode types in storage—can cause confusion

## Quick Reference - Critical Points

- Match polarity to electrode: Most common rods use DCEP or AC
- Start with 1 amp per .001" electrode diameter (1/8" = 125A)
- Maintain arc length equal to electrode diameter
- Use 5-15° drag angle for most applications
- Listen for steady, crisp bacon-frying sound
- Store low-hydrogen rods (7018) in heated oven
- Clean base metal—wire brush minimum, grinder better
- Use smallest electrode that provides needed penetration
- Practice on scrap before production welding
- Chip slag completely between passes on multi-pass welds